

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA** **0+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA** **0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+134**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Lojajar - Krikilan



LOKASI : **STA 1+140**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+150**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
277	Lojajar - Krikilan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 11 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1