

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+014

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+328**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 1+335

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 1+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 1+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 1+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 1+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 278

LOSARI - WATUKANGSI



LOKASI : STA 1+852

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
278	LOSARI - WATUKANGSI			12