

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 028

PAPRINGAN - SAPEN



LOKASI : STA 0+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 13.4 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+011

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
028	PAPRINGAN - SAPEN			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 028

PAPRINGAN - SAPEN



LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
028	PAPRINGAN - SAPEN			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 028

PAPRINGAN - SAPEN



LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+400

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
028	PAPRINGAN - SAPEN			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 028

PAPRINGAN - SAPEN



LOKASI : STA 0+490

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
028	PAPRINGAN - SAPEN			4