

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 13.5 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+008**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 9.4 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 10.5 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+110**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 10.5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+121**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 10.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+159**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Tanen - Banteng**



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 9 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+633**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 15 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS       | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Tanen - Banteng



LOKASI :                **STA**                **0+600**

KONDISI PERKERASAN :                Rusak Ringan

LEBAR PERKERASAN :                15                M

TYPE PERKERASAN :                Aspal

| NO. RUAS | NAMA RUAS       |                 | PETUGAS SURVEY | HALAMAN |
|----------|-----------------|-----------------|----------------|---------|
| 286      | Tanen - Banteng | DPU Kab. Sleman |                | 7       |