

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI :               **STA               0+000**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       11.5               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+010**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4.5               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI :               **STA               0+069**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4.2               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+077**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4.2               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4.2 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI :               **STA               0+500**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+600**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI :               **STA               0+700**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       4               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+800**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       8.4               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Degolan - Ngemplak**



LOKASI : **STA 0+814**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 35.5 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+820**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 35.5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 288      | Degolan - Ngemplak |                 |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Ngemplak - Ngaglik**



LOKASI : **STA 0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 8.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+052**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 8 M

TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS          | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|--------------------|-----------------|----------------|---------|
| 168      | Ngemplak - Ngaglik |                 |                | 1       |