

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 10.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+007**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+236**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 2.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



22 Okt 2025 15:33
7,744987S 110,431387E
Kabupaten Sleman
#Ruas No 290 #STA 1+388
#Survei Kondisi Jalan #DPU Kab. Sleman



22 Okt 2025 15:35
7,745063S 110,431458E
Sleman Regency
#Ruas No 290 #STA 1+394
#Survei Kondisi Jalan #DPU Kab. Sleman

LOKASI : **STA 1+388**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+394**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



22 Okt 2025 15:37
7,745057S 110,431540E
Kabupaten Sleman
#Ruas No 290 #STA 1+400
#Survei Kondisi Jalan #DPU Kab. Sleman



22 Okt 2025 15:40
7,745018S 110,432113E
Kabupaten Sleman
#Ruas No 290 #STA 1+472
#Survei Kondisi Jalan #DPU Kab. Sleman

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+472**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+581**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



LOKASI : **STA 1+590**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



22 Okt 2025 15:57
7,745073S 110,433950E
Kabupaten Sleman
#Ruas No 290 #STA 1+676
#Survei Kondisi Jalan #DPU Kab. Sleman



22 Okt 2025 15:58
7,745018S 110,433960E
Kabupaten Sleman
#Ruas No 290 #STA 1+685
#Survei Kondisi Jalan #DPU Kab. Sleman

LOKASI : **STA 1+676**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+685**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 13.5 M
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Malangrejo - Kenayang



22 Okt 2025 16:00
7,745070S 110,433967E
Kabupaten Sleman
#Ruas No 290 #STA 1+700
#Survei Kondisi Jalan #DPU Kab. Sleman



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 13.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
290	Malangrejo - Kenayang			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 11 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1