

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 292

MANCASAN KIDUL - MANCASAN LOR



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7.9 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+010

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
292	MANCASAN KIDUL - MANCASAN LOR			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 292

MANCASAN KIDUL - MANCASAN LOR



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
292	MANCASAN KIDUL - MANCASAN LOR			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 292

MANCASAN KIDUL - MANCASAN LOR



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
292	MANCASAN KIDUL - MANCASAN LOR			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 292

MANCASAN KIDUL - MANCASAN LOR



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
292	MANCASAN KIDUL - MANCASAN LOR			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 292

MANCASAN KIDUL - MANCASAN LOR



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+730**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
292	MANCASAN KIDUL - MANCASAN LOR			5