

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+357**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+362**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+365**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+369**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+572**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko-Sopalan



LOKASI : **STA 0+584**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 15 M
TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
294	Karangnongko-Sopalan			7