

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,7 M
TYPE PERKERASAN : Paving

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Paving

LOKASI : **STA 0+530**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA** **1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Paingan



LOKASI : **STA** **1+140**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 14 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
295	Pugeran - Paingan			8