

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 9,9 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 0+009


KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6,5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,3 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,3 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+280

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,3 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 0+300

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,3 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+400

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,3 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 0+500

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+600

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



LOKASI : STA 0+650

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6,1 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+685

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,7 M  
TYPE PERKERASAN : Aspal



LOKASI : STA 0+700

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,7 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 0+800

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,7 M  
TYPE PERKERASAN : Aspal



LOKASI : STA 0+900

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,7 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI : STA 1+000

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,7 M  
TYPE PERKERASAN : Aspal



LOKASI : STA 1+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,7 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 8       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 297

PS KOLOMBO - MANUKAN



LOKASI :           **STA     1+200**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN           :     4,7           M  
TYPE PERKERASAN           :     Aspal

LOKASI :           **STA     1+300**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN           :     8,9           M  
TYPE PERKERASAN           :     Aspal

| NO. RUAS | NAMA RUAS            | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------------|-----------------|----------------|---------|
| 297      | PS KOLOMBO - MANUKAN |                 |                | 9       |