


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+265**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+271**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+350**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+842**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Rogoyudan-Karangjati



LOKASI : **STA 0+846**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
298	Rogoyudan-Karangjati			8