

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+302**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 1+158**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+170**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kutu Patran-Kutu-Raden



LOKASI : **STA 1+172**

LOKASI : **STA**

KONDISI PERKERASAN : Rusak Ringan

KONDISI PERKERASAN :

LEBAR PERKERASAN : 7 M

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
299	Kutu Patran-Kutu-Raden	DPU Kab. Sleman		9