

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palembang - Sodomaran



LOKASI : **STA 1+227**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Sodomaran			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Palem Gurih- Somodaran



LOKASI : **STA 1+318**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 1+332**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
305	Palem Gurih- Somodaran			9