

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko - Gamping Kidul



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+007**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
306	Karangnongko - Gamping Kidul			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko - Gamping Kidul



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
306	Karangnongko - Gamping Kidul			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko - Gamping Kidul



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
306	Karangnongko - Gamping Kidul			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karangnongko - Gamping Kidul



LOKASI : **STA 0+445**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
306	Karangnongko - Gamping Kidul			4