

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS 309	NAMA RUAS JANTI - GOWOK	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN 5
-----------------	----------------------------	-----------------	----------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,1 M
TYPE PERKERASAN : Aspal

NO. RUAS 309	NAMA RUAS JANTI - GOWOK	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN 6
-----------------	----------------------------	-----------------	----------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : STA 1+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+148


KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 10,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 309

JANTI - GOWOK



LOKASI : STA 1+180

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10,2 M
TYPE PERKERASAN : Aspal

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
309	JANTI - GOWOK			8