

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 8,7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+072**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+178**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+223**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+250**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7,1 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+336**

KONDISI PERKERASAN : Rusak Ringan



LEBAR PERKERASAN : 7,1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beran - TPU Seyegan



LOKASI : **STA 0+340**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7,1 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :

LEBAR PERKERASAN :

TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
313	Beran - TPU Seyegan			6