

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gejayan - Onggojayan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
321	Gejayan - Onggojayan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gejayan - Onggojayan



LOKASI : **STA 0+022**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
321	Gejayan - Onggojayan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gejayan - Onggojayan



LOKASI : **STA** **0+140**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
321	Gejayan - Onggojayan			3