


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+630**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+090**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Majasem - Sorogedug



LOKASI : **STA 1+095**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
324	Majasem - Sorogedug			8