

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+000

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 6 M

CATATAN : ASPAL

LOKASI : STA 0+005

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+055

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5 M

CATATAN : ASPAL

LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4 M

CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+175

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : ASPAL



LOKASI : STA 0+200

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+230

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6.5 M
CATATAN : ASPAL



LOKASI : STA 0+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6.5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

LOKASI : STA 0+500

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+525

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

LOKASI : STA 0+600

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+615

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

LOKASI : STA 0+635

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5 M
CATATAN : ASPAL

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : JL. KRAPYAK - PS. SLEMAN



LOKASI : STA 0+660

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.5 M
CATATAN : ASPAL

LOKASI : STA

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
CATATAN :

NO. RUAS	NAMA RUAS	DPUPR KABUPATEN SLEMAN	PETUGAS SURVEY	HALAMAN
326	JL. KRAPYAK - PS. SLEMAN			8