

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglemponsari - Kentungan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglemponsari - Kentungan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglemponsari - Kentungan



LOKASI : **STA 0+095**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglemponsari - Kentungan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.9 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+420**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 2.9 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+188**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Paving

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Paving

LOKASI : **STA 1+268**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA 2+070**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+073**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nglempongsari - Kentungan



LOKASI : **STA** **2+070**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 7.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	PETUGAS SURVEY	HALAMAN
328	Nglempongsari - Kentungan	DPU Kab. Sleman	15