

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Monjali-Jongkang



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
329	Monjali-Jongkang			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Monjali-Jongkang



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
329	Monjali-Jongkang			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Monjali-Jongkang



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
329	Monjali-Jongkang			3

FOTO SURVEY KONDISI JALAN TAHUN 2025


RUAS JALAN : Monjali-Jongkang



LOKASI : **STA 0+404**

03:01

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10 M
TYPE PERKERASAN : Aspal



LOKASI : **STA**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
329	Monjali-Jongkang			4