

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 40 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+020**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+400

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 0+500

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11,8 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+520

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 0+600

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+700

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 0+800

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+900

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 1+000

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal



LOKASI : STA 1+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 330

BULAKSUMUR - KARANGMALANG



LOKASI : STA 1+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal



LOKASI : STA 1+290

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 27 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
330	BULAKSUMUR - KARANGMALANG			8