

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 331

DERESAN - KARANGGAYAM



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+012

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
331	DERESAN - KARANGGAYAM			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 331

DERESAN - KARANGGAYAM



LOKASI : STA 0+100

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5,4 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
331	DERESAN - KARANGGAYAM			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 331

DERESAN - KARANGGAYAM



LOKASI : STA 0+300

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
331	DERESAN - KARANGGAYAM			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 331

DERESAN - KARANGGAYAM



LOKASI : STA 0+410

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8,4 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+400

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
331	DERESAN - KARANGGAYAM			4