

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+012**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+150**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 5.8 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+287**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.2 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.2 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+347**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 6.4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7.4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+494**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+589**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+760**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+903**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jambusari-Jene



LOKASI : **STA 0+923**

LOKASI : **STA**

KONDISI PERKERASAN : Sedang

KONDISI PERKERASAN :

LEBAR PERKERASAN : 22.5 M

LEBAR PERKERASAN :

TYPE PERKERASAN : Aspal

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
46	Jambusari-Jene	DPU Kab. Sleman		9