

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nanggulan - Sambilegi Lor



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
337	Nanggulan - Sambilegi Lor			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nanggulan - Sambilegi Lor



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
337	Nanggulan - Sambilegi Lor			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nanggulan - Sambilegi Lor



LOKASI : **STA** **0+280**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
337	Nanggulan - Sambilegi Lor			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nanggulan - Sambilegi Lor



LOKASI : **STA** **0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
337	Nanggulan - Sambilegi Lor			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Nanggulan - Sambilegi Lor



LOKASI : **STA** **0+540**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 11,3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
337	Nanggulan - Sambilegi Lor			5