


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wonokerso - Ngepos



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+003**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 8.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
338	Wonokerso - Ngepos			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wonokerso - Ngepos



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
338	Wonokerso - Ngepos			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wonokerso - Ngepos



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
338	Wonokerso - Ngepos			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wonokerso - Ngepos



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
338	Wonokerso - Ngepos			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wonokerso - Ngepos



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+710**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
338	Wonokerso - Ngepos			5