

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7.3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+174**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+178**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.7 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 2.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+605**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.6 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 0+914**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.3 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+918**

KONDISI PERKERASAN : Rusak Ringan


LEBAR PERKERASAN : 3.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 1+329**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+333**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kadisono - Jurugan



LOKASI : **STA 1+330**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
340	Kadisono - Jurugan			12