

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+020**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+045**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+730**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 8,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+736**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **1+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA** **1+660**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+670**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Karanggayam - Nologaten



LOKASI : **STA 1+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 6,8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+910**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
35	Karanggayam - Nologaten			14