

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jl. Candi Sari



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
156.6	Jl. Candi Sari			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jl. Candi Sari



LOKASI : **STA 0+172**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
156.5	Jl. Candi Sari			1