


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banyumeneng-Patran



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
359	Banyumeneng-Patran			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banyumeneng-Patran



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
359	Banyumeneng-Patran			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banyumeneng-Patran



LOKASI : **STA 0+218**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4.9 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+220**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 7.5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
359	Banyumeneng-Patran			3