

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Seturan - Babatsari



LOKASI : **STA** **0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA** **0+020**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
361	Seturan - Babatsari			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Seturan - Babatsari



LOKASI : **STA** **0+055**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
361	Seturan - Babatsari			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Seturan - Babatsari



LOKASI : **STA** **0+110**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 14 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
361	Seturan - Babatsari			3