

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 10,3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : RusaK Ringan
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+577**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+594**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+308**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+779**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+788**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11,3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pundung - Kradon



LOKASI : **STA 1+790**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 11,3 M

TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN

LEBAR PERKERASAN

TYPE PERKERASAN

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
362	Pundung - Kradon			13