

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+014**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,2 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2,4 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2,4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+965**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 0+985**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3,0 M
 TYPE PERKERASAN : Aspal


LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3,0 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3,0 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 3,0 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,0 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+331**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 2+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+622**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			16

FOTO SURVEY KONDISI JALAN 2025

RUAS JALAN : Ngerank - Klanci



LOKASI : **STA 2+638**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 21 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+640**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 21 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
363	Ngerank - Klanci			17