

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wadas - Sucen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 17 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+030**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
366	Wadas - Sucen			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wadas - Sucen



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 7.1 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
366	Wadas - Sucen			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wadas - Sucen



LOKASI : **STA 0+290**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+298**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7.3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
366	Wadas - Sucen			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Wadas - Sucen



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 7.3 M

TYPE PERKERASAN : Aspal



NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
366	Wadas - Sucen			4