


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 370

LAP. RADEN RONGGO - GLONDONG



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 6,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
266	DAWUKAN - CEPOR			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 370

DAWUKAN - CEPOR



LOKASI : **STA 0+170**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
266	DAWUKAN - CEPOR			2