

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bulu - Krapyak



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 16,3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
371	Bulu - Krapyak			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bulu - Krapyak



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
371	Bulu - Krapyak			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bulu - Krapyak



LOKASI : **STA 0+242**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+259**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
371	Bulu - Krapyak			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Bulu - Krapyak



LOKASI : **STA 0+260**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 13,2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 64**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
371	Bulu - Krapyak			4