

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : STA 0+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 24 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+010


KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 9,2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : STA 0+045

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7,1 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+100

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7,1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : STA 0+200

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7,1 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+300

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : STA 0+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal



LOKASI : STA 0+500

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : **STA 0+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : **STA 0+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : 038

KLEBENGAN - SAMIRONO



LOKASI : **STA 1+137**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 23 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+150**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 23 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
038	KLEBENGAN - SAMIRONO			8