

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 9.3 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+010**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Pugeran - Kayen



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+950**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 20 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
45	Pugeran - Kayen			11