

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 11.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+567**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+854**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+862**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+895**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA 0+900**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA** **1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **1+129**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 7.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Klodran-Setan



LOKASI : **STA** **1+140**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 20 M
TYPE PERKERASAN : Aspal

LOKASI : **STA**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
46	Klodran-Setan			10