

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.8 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+010**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+700**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.9 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.9 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.3 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.6 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : STA 1+100

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

LOKASI : STA 1+107

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 6.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mlandangan - Karangasem



LOKASI : STA 1+113

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 9.3 M
TYPE PERKERASAN : Aspal

LOKASI : STA 0+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 9.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
48	Mlandangan - Karangasem			8