


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+005**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.4 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA** **0+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **0+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA** **0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA** **1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+147**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 1+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+500**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA 1+600**

KONDISI PERKERASAN : **Rusak Ringan**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Rusak Ringan**
LEBAR PERKERASAN : 4.3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA** **1+750**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal


LOKASI : **STA** **1+755**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 10.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Gandok - Plosokuning



LOKASI : **STA** **1+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 10.2 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
51	Gandok - Plosokuning			12