


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 9.4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+008**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 3.3 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.6 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan

LEBAR PERKERASAN : 4.8 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.8 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA 0+876**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.7 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+889**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 16.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Kayen - Karanganyar



LOKASI : **STA** **0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 16.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
54	Kayen - Karanganyar			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ngemplak - Ngaglik



LOKASI : **STA 0+000**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 11 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 0+031**

KONDISI PERKERASAN :

LEBAR PERKERASAN : 4.1 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
168	Ngemplak - Ngaglik			1