

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Soropadan Karanggayam



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 7.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+020**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4,3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
64	Soropadan Karanggayam			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Soropadan Karanggayam



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4,3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5,7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
64	Soropadan Karanggayam			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Soropadan Karanggayam



LOKASI : **STA** **0+210**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 11,8 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
64	Soropadan Karanggayam			3