

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jragung-Blambangan



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+006**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
65	Jragung-Blambangan			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jragung-Blambangan



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
65	Jragung-Blambangan			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jragung-Blambangan



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
65	Jragung-Blambangan			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jragung-Blambangan



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3.9 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+575**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
65	Jragung-Blambangan			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Jragung-Blambangan



LOKASI : **STA 0+580**

LOKASI : **STA**

KONDISI PERKERASAN : Rusak Ringan

KONDISI PERKERASAN :

LEBAR PERKERASAN : 5.6 M

LEBAR PERKERASAN : M

TYPE PERKERASAN : Aspal

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS		PETUGAS SURVEY	HALAMAN
65	Jragung-Blambangan	DPU Kab. Sleman		5