



FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 12 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+012**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+700**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Rusak Ringan**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Rusak Ringan**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 1+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 2+100**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
 LEBAR PERKERASAN : 4.1 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 2+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 4.1 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+507**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Mindi - Punthuk



LOKASI : **STA 2+518**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 10 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 10 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
68	Mindi - Punthuk			15