

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 12.2 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+014**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+660**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6.2 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+679**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 0+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+100**

KONDISI PERKERASAN : **Rusak Ringan**
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal


LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Rusak Ringan**
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+400**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+426**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 6 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+435**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 1+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 2+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+362

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 2+368

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 2+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 2+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal




LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			18


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 2+900

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+000

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 3+100

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+152

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.7 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 3+168

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+200

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			21


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 3+300

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal




LOKASI : STA 3+400

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			22


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 3+500

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal



LOKASI : STA 3+600

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			23

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : STA 3+700

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal




LOKASI : STA 3+800

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			24


FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 3+900**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5.5 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 4+000**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 7.5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			25

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarharjo - Ngemplak



LOKASI : **STA 4+007**

KONDISI PERKERASAN : Sedang
 LEBAR PERKERASAN : 18 M
 TYPE PERKERASAN : Aspal



NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
69	Banjarharjo - Ngemplak			26