

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 0+200**

KONDISI PERKERASAN : **Sedang**
LEBAR PERKERASAN : 4 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+700**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 0+800**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 4.5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 6 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 1+241**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 6 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 1+258**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 6 M
 TYPE PERKERASAN : Aspal



LOKASI : **STA 1+300**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : 5 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+412**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Sembungan - Kiyaran



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 9,4 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPU Kab. Sleman	PETUGAS SURVEY	HALAMAN
74	Sembungan - Kiyaran			10