


## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :               **STA               0+000**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       6.5               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+100**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       6.3               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :               **STA               0+200**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       6.3               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+236**

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN :       5.6               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :               **STA               0+300**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       5.6               M  
TYPE PERKERASAN :       Aspal

LOKASI :               **STA               0+303**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       5.6               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :               **STA               0+400**

KONDISI PERKERASAN :       Rusak Ringan  
LEBAR PERKERASAN :       5.6               M  
TYPE PERKERASAN :       Aspal


LOKASI :               **STA               0+500**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN :       6               M  
TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :           **STA           0+600**

KONDISI PERKERASAN :       **Sedang**  
 LEBAR PERKERASAN :       6           M  
 TYPE PERKERASAN :       Aspal

LOKASI :           **STA           0+700**

KONDISI PERKERASAN :       Rusak Ringan  
 LEBAR PERKERASAN :       6           M  
 TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI :           **STA           0+800**

KONDISI PERKERASAN :       Rusak Ringan  
 LEBAR PERKERASAN :       6           M  
 TYPE PERKERASAN :       Aspal

LOKASI :           **STA           0+900**

KONDISI PERKERASAN :       **Sedang**  
 LEBAR PERKERASAN :       6           M  
 TYPE PERKERASAN :       Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI : **STA 1+000**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Banteng - Karanggeneng**



LOKASI : **STA 1+140**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 8 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 8 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS              | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|------------------------|-----------------|----------------|---------|
| 78       | Banteng - Karanggeneng |                 |                | 8       |