


## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 8 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+011**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5.5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 1       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5.4 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5.4 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 2       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5.5 M  
TYPE PERKERASAN : Aspal



LOKASI : **STA 0+366**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 7 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 3       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 0+387**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 7 M  
TYPE PERKERASAN : Aspal




LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5.6 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 4       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA                0+500**

KONDISI PERKERASAN                :                **Sedang**  
LEBAR PERKERASAN                :                5.1                M  
TYPE PERKERASAN                :                Aspal

LOKASI :                **STA                0+600**

KONDISI PERKERASAN                :                Baik  
LEBAR PERKERASAN                :                5.1                M  
TYPE PERKERASAN                :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 5       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA                0+700**

KONDISI PERKERASAN                :                Sedang  
LEBAR PERKERASAN                :                5.1                M  
TYPE PERKERASAN                :                Aspal

LOKASI :                **STA                0+800**

KONDISI PERKERASAN                :                Sedang  
LEBAR PERKERASAN                :                5                M  
TYPE PERKERASAN                :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 6       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA                0+900**

KONDISI PERKERASAN                :                Sedang  
LEBAR PERKERASAN                :                5.1                M  
TYPE PERKERASAN                :                Aspal

LOKASI :                **STA                1+000**

KONDISI PERKERASAN                :                Sedang  
LEBAR PERKERASAN                :                5.2                M  
TYPE PERKERASAN                :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 7       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA                1+100**

KONDISI PERKERASAN                :                Rusak Ringan  
LEBAR PERKERASAN                :                5.2                M  
TYPE PERKERASAN                :                Aspal

LOKASI :                **STA                1+200**

KONDISI PERKERASAN                :                Sedang  
LEBAR PERKERASAN                :                5.2                M  
TYPE PERKERASAN                :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 8       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA**                **1+300**

KONDISI PERKERASAN :                **Sedang**  
LEBAR PERKERASAN :                5.2                M  
TYPE PERKERASAN :                Aspal

LOKASI :                **STA**                **1+400**

KONDISI PERKERASAN :                **Sedang**  
LEBAR PERKERASAN :                5                M  
TYPE PERKERASAN :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 9       |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Krikilan-Gandu



LOKASI :                **STA**                **1+500**

KONDISI PERKERASAN :                **Sedang**  
LEBAR PERKERASAN :                5.1                M  
TYPE PERKERASAN :                Aspal

LOKASI :                **STA**                **1+600**

KONDISI PERKERASAN :                Rusak Ringan  
LEBAR PERKERASAN :                5.1                M  
TYPE PERKERASAN :                Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 10      |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 1+700**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+800**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 11      |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 1+900**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 2+000**

KONDISI PERKERASAN : **Sedang**  
LEBAR PERKERASAN : 5 M  
TYPE PERKERASAN : Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 12      |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI :               **STA               2+100**

KONDISI PERKERASAN               :       Rusak Ringan  
LEBAR PERKERASAN               :       5.2               M  
TYPE PERKERASAN               :       Aspal

LOKASI :               **STA               2+200**

KONDISI PERKERASAN               :       Rusak Ringan  
LEBAR PERKERASAN               :       5.2  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 13      |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI :               **STA               2+300**

KONDISI PERKERASAN               :       Rusak Ringan  
LEBAR PERKERASAN               :       5.1               M  
TYPE PERKERASAN               :       Aspal

LOKASI :               **STA               2+400**

KONDISI PERKERASAN               :       Sedang  
LEBAR PERKERASAN               :       5.1               M  
TYPE PERKERASAN               :       Aspal

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 14      |

## FOTO SURVEY KONDISI JALAN TAHUN 2025

**RUAS JALAN : Krikilan-Gandu**



LOKASI : **STA 2+500**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 5.1 M  
TYPE PERKERASAN : Aspal



LOKASI : **STA 2+527**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 5.2 M  
TYPE PERKERASAN :

| NO. RUAS | NAMA RUAS      | DPU Kab. Sleman | PETUGAS SURVEY | HALAMAN |
|----------|----------------|-----------------|----------------|---------|
| 98       | Krikilan-Gandu |                 |                | 15      |